

date  
projectname  
attn  
from  
fax  
email  
phone

1/27/2017  
HOMEWOOD SUITES  
CHELSEA JUNGLES  
CARMEN MATHIS  
502-805-0509  
c.mathis@mathisinc.com  
502-664-8469

## Care, Cleaning, and Maintenance Instructions - Solid Plastic Partitions

Routine cleaning of dirt and grime should be performed with a soft wet cloth. Stubborn dirt and grease can be removed by using any non-abrasive household cleaning agent.

Graffiti can be removed by using an industrial graffiti remover. It is best to test a small subtle area before applying an industrial graffiti remover, as some cleaners can harm your plastic surface.

Mineral spirits or acetone may be used to remove any masking residue that may have adhered to the product after installation.

Do not use any form of abrasive cleaners or pads on your solid plastic toilet partitions. These products will leave scratch marks and will remove the sheen from the surface.

Regularly tighten any fasteners that may have become loose as a result of vibrations, vandalism, or misuse.

Most cuts and scratches can be repaired by burnishing the affected surface with a smooth round object, such as a spoon, or the rounded edges of a screwdriver handle. While utilizing the rounded edge of the tool, apply pressure to the cut or scratched surface to heal the plastic.

After cleaning, silicone can be applied to the plastic surface to brighten the finish.

## Washroom Partitions - Solid Plastic



Moonlight Granite



Beige



Sage Green



Grey



Linen



Mocha



Forest Green



Slate




Sandstorm



Parchment



Burgundy



Black Matrix



Royal Blue








Black

**Note: Color charts are printed approximations--actual colors may vary. Please contact AJW to request a sample.**

# Single Ear Continuous Stainless Steel Bracket





## Stainless Steel Partitions



- **Material:** 18 ga. Stainless Steel, #4 Satin Finish.
- **Application:** Wall-to-panel connections; panel-to-pilaster connections. 1 1/4" brackets for wall-to-pilaster connections.
- **Fasteners required per component:** (10) 1 1/2" Torx screws **or** (10) 3/4" Torx screws; (5) male/female thru-bolt pairs.


# Double Ear Continuous Stainless Steel Bracket

## Stainless Steel Partitions




- **Material:** 18 ga. Stainless Steel, #4 Satin Finish.
- **Application:** Wall-to-panel connections; panel-to-pilaster connections.
- **Fasteners required per component:** (10) 1 1/2" Torx screws **or** (10) 3/4" Torx screws; (5) male/female thru-bolt pairs.

## Door Pull



### Sample Elevation



- **Material:** Chrome Plated Zamac.
- **Application:** (1) per door.
- **Fasteners required per component:** (2)  $1\frac{3}{8}"$  male machine bolts (connects to slide latch on opposite side of the door).



## Warranty – Solid Plastic Partitions

Subject to the terms set out in this warranty, AJW guarantees its solid plastic toilet partitions to be free from manufacturing defects in material and workmanship, and free of breakage, corrosion, and delamination of all plastic components for **a period of (25) years** from the date of shipment.

This warranty is for material supplied by AJW only, and only applies to the original installation of the toilet partitions, installed in accordance with AJW's written installation instructions and drawings. AJW's recommendations for proper handling, storage, cleaning, and maintenance must be followed for this warranty to be valid.

This warranty excludes defects in the partition caused by: vandalism, improper usage, improper installation, neglect, or failure in the structure of the building. Regular maintenance is required for the partition warranty to be valid.

If the solid plastic toilet partition system is found to be defective in workmanship or materials within (25) years from the date of shipment, AJW will replace all affected solid plastic components, free of charge. AJW will not be responsible for any expenses including, but not limited to the removal, installation costs, or any other costs associated with the repair or replacement of the partition.

The replacement or repair of defective material as stated in this warranty shall constitute the sole remedy of the buyer and the sole liability of AJW under this warranty. AJW shall not be liable for any incidental, consequential or indirect damages caused by the failure or defect in the material supplied, or any delay in the replacement or repair of warranty items.

Warranty claims must be made during the warranty period, and communicated to AJW by contacting AJW Architectural Products at 509 Temple Hill Road – New Windsor, NY 12553 - Phone: 845-562-3332.